
MA900 SORTING MODES





 For best efficiency, do not exceed sort speeds described in the nozzle selection guide

